STANDARD 10"-24" HIGH LIFT FLANGE WELD TEST PLUG OPERATING INSTRUCTIONS

These operating instructions give step by step instructions on the use of the High Lift Flange Weld Test Plug. These plugs can be used in two different configurations as a testing plug and a welding plug. The test plug configuration allows the flange to pipe weld to be tested after welding. The weld plug configuration aids in the welding of the flange to pipe while monitoring upstream pressure and also allows the weld to be tested after welding. Follow steps labeled **TP** for test plug configuration, **WP** for weld plug configuration and **TP WP** for both.

WARNING!

- PRESSURE TESTING IS INHERENTLY DANGEROUS. <u>STRICT ADHERENCE</u> TO THESE OPERATION INSTRUCTIONS AND INDUSTRY SAFETY PRACTICES COULD PREVENT INJURY TO PERSONNEL.
- ALL PERSONNEL MUST BE CLEAR OF TEST PLUG WHEN PRESSURE TESTING.
- FOR SAFETY, AN INCOMPRESSIBLE LIQUID SUCH AS WATER SHOULD BE USED AS THE TEST MEDIUM, RESIDUAL AIR OR GAS IS TO BE EVACUATED FROM THE PIPE PRIOR TO TESTING.

PRIOR TO USE:

- Verify marking on seal with o-ring and replacement washer is equivalent to the pipe size being tested. They should be marked with the flange size and pipe schedule. The seal and the washer OD is sized approximately ½" smaller than the pipe ID. Replacement washers are required on all sizes except the smallest schedule available. The following sizes do NOT have replacement washers. 10" schedule 100, 12" schedule 80, 14" schedule 140. 16" schedule 120, 18" schedule 120, 20" schedule 100 & 24" schedule 120
- Inspect the raised face (gasket surface) of the Flange Plug and mating flange to be tested. Damage or surface imperfections may result in leakage and should be repaired prior to testing.
- Clean and dry the pipe ID. Remove all moisture, debris and excessive scale.

STEP 1

TP ATTACHMENT OF TEST PLUG TO MATING FLANGE

- Any weld droop or spatter that protrudes into pipe id more than the clearance listed in table 1 must be removed to allow plug installation.
- Apply gasket to mating flange face and position Flange Plug against mating flange. Rotate plug as required locating purge vent at highest point and installing flange bolts. Tighten bolts in a cross-like pattern to properly seal the flange gasket.

WP ATTACHMENT OF WELDING PLUG SET-UP TO MATING FLANGE

Locate the flange to be welded on the pipe using an alignment tool (The Flange Test & Welding Plug is not designed to support or
position flange to be welded). Apply gasket to mating flange face and insert the Flange plug into the flange and pipe with the inert
gas purge ports oriented at the top and bottom of the flange. Tighten bolts in a cross-like pattern to properly seal the flange gasket.

STEP 2

TP WP TIGHTENING AND EXPANSION OF SEAL ELEMENT

- Correct Tightness of hex nut is critical to the operation of the Flange Test & Welding Plug, a leak of the seal is usually an indication the hex nuts were not adequately tightened. The normal torque listed in table 1 should be adequate for most installations, however due to variations within pipe ID finishes the torque may need to be increased up to the maximum torque value listed in table 1. If at the maximum torque the plug still leaks, verify the correct seal and washers are being used. Verify that the seal O-ring is seated correctly in the groove on seal and that the O-ring is not damaged, (10" and 12" plugs only).
- Tighten hex nuts in a cross-like pattern in approx. 100ft/lbs (135.6N-m) increments using an impact wrench until torque specified in Table 1 has been reached. Verify this torque with a calibrated torque wrench. Remove the purge plug closest to highest point. Connect hydro-pump to fill port on Flange. Slowly begin to fill the plug until water flows from the vent. Discontinue water input and install plug leak tight.

STEP 3

WP PREPARATION FOR WELDING

Make connection to upstream monitor port that will clearly indicate an increase of pressure or the presence of dangerous gases. In addition, upstream vapors may be vented by attaching approximately 50 ft. (15.2m) of hose to the vent port, and locating the end of the hose downwind from the weld area.

For normal conditions where Inert Gas Purge is not required:

 Remove pipe plugs from fill and vent plugs on the flange or make connections to fill and vent ports as required by welding safety procedures.

If Inert gas purge is required:



http://estgroup.cwfc.com

- Remove pipe plugs from the fill and vent ports on the flange.
- Connect Inert gas supply to fill port. Make connections to vent port as required to monitor or regulate the flow of inert gas.
- Initiate Inert gas purge and adjust Inert gas pressure regulator as required to maintain a slight positive pressure during welding. As welding proceeds, adjust Inert gas flow as needed to insure weld quality.

STEP 4

WP Welding

- NOTE: do not let the weld protrude into the pipe ID by more than the values listed in Table 1 or grinding of the pipe ID
 may be required for plug removal.
- Begin welding the flange to the pipe while monitoring upstream pressure. Stop welding immediately if the upstream pressure increases which indicates flow in the line. During welding the pipe at the seal location must not become too hot to touch by hand. Should the pipe in the seal location become too hot to touch by hand, discontinue welding and allow pipe too cool.

STEP 5

TP WP HYDROSTATIC PRESSURE TEST

- WARNING! NEVER ATTEMPT TO ADJUST THE FLANGE TEST & WELDING PLUG WHILE UNDER PRESSURE. NEVER EXCEED THE TEST PRESSURES IN TABLE 2
- Remove the vent plug. Connect hydropump to fill port on Flange. Slowly begin to fill the plug until water flows from the vent. Discontinue water input and install the vent plug leak tight. Refer to Table 2 for the maximum test pressure for the Flange Test Plug. The test pressure must never exceed the strength of the weakest component in the system being tested. Slowly introduce the test pressure. If a pressure decay test will be conducted, hold at desired pressure with pump for a minimum of 5 minutes prior to closing isolation valve. This will allow parts to settle. Continue holding the desired pressure to meet testing requirements. If pressure drops off a large amount or a leak between seal and tube id is detected, tighten the hex nut until leak is sealed. (Do not exceed max. installation torque). After the test is completed, release all pressure. Remove the fill and vent plugs to drain water. Remove all testing equipment. Loosen the hex nuts to fully relax seal. Loosen and remove hex nuts and flange mounting bolts. Withdraw the Flange Test Plug from the pipe.

<u>INSPECT PLUG AFTER EACH USE</u> Surface imperfections on the flange face should be fixed prior to further testing. Replace worn or damaged seals and o-rings. Clean and dry prior to storage. Store these instructions with plug.

TABLE 1 High Lift Flange Weld Test Plug Clearance and Suggested Installation Torque Values

r	ı	OLEADANIOE	NODMAI	144 V/114 II 114
FLANGE SIZE	ANSI FLANGE CLASS	CLEARANCE	NORMAL	MAXIMUM
		BETWEEN SEAL OD	INSTALLTION	INSTALLATION
		AND PIPE	TORQUE	TORQUE
	02,100	in (mm)	Ft-lbs (N-m)	Ft-lbs (N-m)
10" DN250	150	1/2 (12.7)	150 (203.4)	600 (813.5)
10" DN250	300	1/2 (12.7)	200 (271.2)	600 (813.5)
10" DN250	600	1/2 (12.7)	300 (406.8)	600 (813.5)
12" DN300	150	1/2 (12.7)	200 (271.2)	600 (813.5)
12" DN300	300	1/2 (12.7)	250 (339.0)	600 (813.5)
12" DN300	600	1/2 (12.7)	300 (406.8)	600 (813.5)
14" DN350	150	1/2 (12.7)	200 (271.2)	600 (813.5)
14" DN350	300	1/2 (12.7)	300 (406.8)	600 (813.5)
14" DN350	600	1/2 (12.7)	300 (406.8)	600 (813.5)
16" DN 400	150	1/2 (12.7)	200 (271.2)	600 (813.5)
16" DN 400	300	1/2 (12.7)	300 (406.8)	600 (813.5)
16" DN 400	600	1/2 (12.7)	300 (406.8)	600 (813.5)
18" DN450	150	1/2 (12.7)	250 (339.0)	600 (813.5)
18" DN450	300	1/2 (12.7)	350 (474.5)	600 (813.5)
18" DN450	600	1/2 (12.7)	350 (474.5)	600 (813.5)
20" DN500	150	1/2 (12.7)	250 (339.0)	600 (813.5)
20" DN500	300	1/2 (12.7)	350 (474.5)	600 (813.5)
20" DN500	600	1/2 (12.7)	350 (474.5)	600 (813.5)
24" DN600	150	1/2 (12.7)	300 (406.8)	600 (813.5)
24" DN600	300	1/2 (12.7)	400 (542.3)	600 (813.5)
24" DN600	600	1/2 (12.7)	400 (542.3)	600 (813.5)



http://estgroup.cwfc.com

TABLE 2. High Lift Flange Weld Test Plug Maximum Test Pressures

	ANSI	MAXIMUM TEST
FLANGE SIZE	FLANGE	PRESSURE
	CLASS	psi (Bar)
10" DN250 - 24" DN600	150	450 (31.0)
10" DN250 - 24" DN600	300	1125 (77.6)
10" DN250 - 12" DN300	600	2250 (155.1)
14" DN350 - 24" DN600	600	1125 (77.6)

REPLACEMENT SEAL & WASHER PROCEDURE

- Remove hex nuts, hardened washers & compression tubes, if present, from Flange Test Plug.
- 2. Remove the flange assembly from the inner tube assembly.
- 3. The seal may now be removed from the inner tube assembly. (The 10" and 12" size seals have o-rings)
- 4. Verify marking on seal and replacement washer is equivalent to the pipe size being tested. They should be marked with the flange size and pipe schedule. Replacement washers are required on all sizes except the smallest schedule available. The following sizes do <u>NOT</u> have replacement washers. 10" schedule 100, 12" schedule 80, 14" schedule 140. 16" schedule 120, 18" schedule 120, 20" schedule 100 & 24" schedule 120
- Install the replacement washer so the radius on outside edge is towards the seal. The replacement washer has an internal chamfer for weld clearance. Ensure this is installed correctly. Install the seal.
- 6. Place the flange assembly back onto the inner tube assembly
- 7. Install the compression tubes, if present, the hardened washers and the hex nuts.
- 8. The Flange Test Plug is ready for testing.

QUESTIONS? Contact EST Group Customer Service at any of the following locations with questions.


In USA and Canada: tel: 800-355-7044, fax: 215-721-1101, e-mail: est-info@curtisswright.com In Europe: tel: +31-172-418841, fax: +31-172-418849; e-mail: est-emea@curtisswright.com In Asia: tel: +65-6745-8560, fax: +65-6742-8700, e-mail: est-asia@curtisswright.com

On the Internet: http://estgroup.cwfc.com

EST Group is a business unit of Curtiss-Wright Flow Control Company. EST Group provides a complete range of repair products, services and replacement parts covering the life cycle of tubular heat exchangers and condensers; additionally EST Group provides products and services to facilitate pressure testing pipe, piping systems, pressure vessels and their components. Visit EST Group on the Internet at http://estgroup.cwfc.com.

REPLACEMENT PART LIST				
I LI EAGEMENT I ART EIGT				
	PIPE	REPLACEMENT	O-RING	REPLACEMENT SEAL
PIPE SIZE	SCHEDULE	SEAL PART	DASH	& WASHER SET PART
	SCHEDULE	NUMBER	NUMBER	NUMBER
10	sch 100	HL-10P100-RS	-445	N/A
10	sch 80	HL-10P80-RS	-446	HL-10P80-SW
10	sch 60/xs	HL-10PXSRS	-446	HL-10PXS-SW
10	sch 40/std	HL-10P40-RS	-447	HL-10P40-SW
10	sch 30	HL-10P30-RS	-447	HL-10P30-SW
10	sch 20	HL-10P20-RS	-447	HL-10P20-SW
10	sch 10s	HL-10P10S-RS	-448	HL-10P10S-SW
10	sch 5	HL-10P5-RS	-448	HL-10P5-SW
12	sch 80	HL-12P80-RS	-449	N/A
12	sch 60	HL-12P60-RS	-450	HL-12P60-SW
12	XS	HL-12PXS-RS	-450	HL-12PXS-SW
12	sch40/std	HL-12P40-RS	-451	HL-12P40-SW
12	sch 30	HL-12P30-RS	-451	HL-12P30-SW
12	sch 20	HL-12P20-RS	-451	HL-12P20-SW
12	sch10s/ 5	HL-12P10S-RS	-452	HL-12P10S-SW
14	sch 140	HL-14P140-RS	N/A	N/A
14	sch 120	HL-14P120-RS	N/A	HL-14P120-SW
14	sch 100	HL-14P100-RS	N/A	HL-14P100-SW
14	sch 80	HL-14P80-RS	N/A	HL-14P80-SW
14	sch 60	HL-14P60-RS	N/A	HL-14P60-SW
14	XS	HL-14PXS-RS	N/A	HL-14PXS-SW
14	sch 40	HL-14P40-RS	N/A	HL-14P40-SW
14	sch 30/std	HL-14PSTD-RS	N/A	HL-14PSTD-SW
14	sch 20	HL-14P20-RS	N/A	HL-14P140-SW
14	sch 10/10s/5	HL-14P10-RS	N/A	HL-14P140-SW
16	sch 120	HL-16P120-RS	N/A	N/A
16	sch 100	HL-16P100-RS	N/A	HL-16P100-SW
16	sch 80	HL-16P80-RS	N/A	HL-16P80-SW
16	sch 60	HL-16P60-RS	N/A	HL-16P60-SW
16	sch 40/xs	HL-16P40-RS	N/A	HL-16P40-SW
16	sch 30/std	HL-16PSTD-RS	N/A	HL-16PSTD-SW
16	sch 20	HL-16P20-RS	N/A	HL-16P20-SW
16	sch 10/10s/5	HL-16P10-RS	N/A	HL-16P10-SW

REPLACEMENT PART LIST					
PIPE SIZE	PIPE SCHEDULE	REPLACEMENT SEAL PART NUMBER	O-RING DASH NUMBER	REPLACEMENT SEAL & WASHER SET PART NUMBER	
18	sch 120	HL-18P120-RS	N/A	N/A	
18	sch 100	HL-18P100-RS	N/A	HL-18P100-SW	
18	sch 80	HL-18P80-RS	N/A	HL-18P80-SW	
18	sch 60	HL-18P60-RS	N/A	HL-18P60-SW	
18	sch 40	HL-18P40-RS	N/A	HL-18P40-SW	
18	XS	HL-18PXS-RS	N/A	HL-18PXS-SW	
18	sch 30	HL-18P30-RS	N/A	HL-18P30-SW	
18	std	HL-18PSTD-RS	N/A	HL-18PSTD-SW	
18	sch 20	HL-18P20-RS	N/A	HL-18P20-SW	
18	sch 10/10s/5	HL-18P10-RS	N/A	HL-18P10-SW	
20	sch 100	HL-20P100-RS	N/A	N/A	
20	sch 80	HL-20P80-RS	N/A	HL-20P80-SW	
20	sch 60	HL-20P60-RS	N/A	HL-20P60-SW	
20	sch 40	HL-20P40-RS	N/A	HL-20P40-SW	
20	sch 30/xs	HL-20PXS-RS	N/A	HL-20PXS-SW	
20	sch 20/std	HL-20PSTD-RS	N/A	HL-20PSTD-SW	
20	sch 10	HL-20P10-RS	N/A	HL-20P10-SW	
24	sch 120	HL-24P120-RS	N/A	N/A	
24	sch 100	HL-24P100-RS	N/A	HL-24P100-SW	
24	sch 80	HL-24P80-RS	N/A	HL-24P80-SW	
24	sch 60	HL-24P60-RS	N/A	HL-24P60-SW	
24	sch 40	HL-24P40-RS	N/A	HL-24P40-SW	
24	sch 30	HL-24P30-RS	N/A	HL-24P30-SW	
24	XS	HL-24PXS-RS	N/A	HL-24PXS-SW	
24	sch 20/std	HL-24PSTD-RS	N/A	HL-24PSTD-SW	
24	sch 10/5	HL-24P10-RS	N/A	HL-24P10-SW	





EST Group 2701 Township Line Rd Hatfield, PA 19440-1770 USA (P) 215.721.1100 800.355.7044 (F) 215.721.1101 est-info@curtisswright.com

http://estgroup.cwfc.com

Europe / Middle East / Africa EST Group B.V. Hoorn 312a 2404 HL Alphen aan den Rijn The Netherlands (P) +31.172.418841 (F) +31.172.418849 est-emea@curtisswright.com Asia
EST Group Asia
35 Tannery Rd, #11-10 Tannery Block
Ruby Industrial Complex
Singapore 247740
(P) +65.6745.8560
(F) +65.6742.8700
est-asia@curtisswright.com